

Display Set-Up

Step 1

Begin by removing all parts from the box and place on a clean, flat surface.

Layout the Frame (3) and both of the Vertical Poles (2) as shown below. Screw the Vertical Poles (2) onto the Fixed Screws on the bottom of the Frame (3).





Step 3

Stand the assembled unit upright.

Slide the Graphic into the Graphic Slit and guide it until it rests at the bottom.

Your display is now complete and ready for use.

Storage & Care

Place all product parts into shipping box and store in a cool, dry location. To clean, wipe with damp cloth.

Step 2

Feed the Screws (5) through the indented side of the Base Screw Holes.

Insert the Screws (5) into the Vertical Poles (2) and tighten with the Hex Wrench (4).





